

HyChill HR22/502

Pressure Temperature Chart

Temperature		HR22/502		R22		R502	
°C	°F	kPa	psi	kPa	psi	kPa	psi
-40	-40	48	7	5	1	30	4
-38	-36	61	9	15	2	41	6
-36	-33	74	11	26	4	54	8
-34	-29	87	13	37	5	68	10
-32	-26	101	15	50	7	82	12
-30	-22	117	17	63	9	98	14
-28	-18	133	19	78	11	114	17
-26	-15	149	22	93	14	132	19
-24	-11	168	24	109	16	150	22
-22	-8	187	27	126	18	170	25
-20	-4	207	30	145	21	191	28
-18	0	228	33	164	24	213	31
-16	3	250	36	185	27	236	34
-14	7	274	40	207	30	261	38
-12	10	298	43	230	33	287	42
-10	14	324	47	252	37	314	46
-8	18	351	51	280	41	343	50
-6	21	380	55	307	45	373	54
-4	25	409	60	336	49	405	59
-2	28	441	64	366	53	438	64
0	32	473	69	397	58	473	69
2	36	503	74	431	63	510	74
4	39	541	79	465	68	548	80
6	43	578	84	502	73	588	86
8	46	616	90	540	79	629	92
10	50	656	96	580	85	673	98
12	54	698	102	622	91	718	105
14	57	741	108	666	97	766	112
16	61	786	115	712	104	815	119
18	64	833	121	760	111	866	126
20	68	881	128	810	118	920	134
22	72	932	136	862	126	975	142
24	75	984	143	916	133	1033	150
26	79	1038	151	972	142	1092	159
28	82	1092	159	1031	150	1154	168
30	86	1150	168	1092	159	1219	178
32	90	1209	176	1155	168	1285	187
34	93	1272	185	1221	178	1355	197
36	97	1337	195	1289	188	1426	208
38	100	1403	205	1360	198	1500	219
40	104	1472	215	1433	209	1577	230
42	108	1543	225	1509	220	1656	241
44	111	1615	235	1588	232	1738	253
46	115	1689	246	1670	243	1823	266
48	118	1768	258	1754	256	1911	278
50	122	1848	269	1842	269	2001	292
52	126	1929	281	1932	282	2095	305
54	129	2013	293	2026	295	2191	319
56	133	2100	306	2123	309	2291	334